

June 2, 2015

US EPA Region 1 FOSC
Emergency Response Section
One Congress Street, Suite 1100 (HBR)
Boston, Massachusetts 02114-2023


**RE: ExxonMobil Oil Corporation – Everett, MA Terminal
Facility Response Plan - 5 Year Review
EPA FRP#: 01MA0118**

To Whom It May Concern:

On behalf of ExxonMobil Oil Corporation, enclosed is an updated copy number EVE-6 of the above referenced Plan. The Plan has been revised through May 2015 as a result of a 5 year review. This copy replaces any copies you currently maintain for this Facility.

If you have any questions or comments, please contact me at (b) (6).

Sincerely,



John K. Carroll III
Vice President, Compliance Services

Enclosure

QUALIFIED INDIVIDUAL**Certification:**

The Company grants full authority to the designated Qualified and Alternate Qualified Individuals to implement the Facility Response Plan and to:

- Activate and engage in contracting with oil spill removal organizations,
- Act as liaison with the pre-designated Federal On-Scene Coordinator (FOSC), and
- Obligate funds required to carryout response activities.

Qualified Individual:

Jason Pociask

52 Beacham Street

(b) (6)

(Home)

Terminal Superintendent/ QI/ Everett, Massachusetts

(b) (6)

(Cellular)

IC

Training Comments: Training is addressed in App. D.3. Training records are maintained at the site.

Alt. Qualified Individual:

Gail Prizio

52 Beacham Street

(b) (6)

(Home)

Field Operations Specialist/ Everett, Massachusetts

(b) (6)

(Cellular)

AQI

Training Comments: Training is addressed in App. D.3. Training records are maintained at the site.

Alt. Qualified Individual:

Jay Smith

52 Beacham Street

(b) (6)

(Home)

Terminal Supervisor/ AQI Everett, Massachusetts

(b) (6)

(Cellular)

Training Comments: Training is addressed in App. D.3. Training records are maintained at the site.

6.5 VULNERABILITY ANALYSIS

Water Intakes

Water intakes are a critical resource and may be vulnerable to spills. Water intakes located within the planning distance are shown in the following table:

WATER INTAKE	LOCATION/DISTANCE
(b) (7)(F)	(b) (7)(F)
(b) (7)(F)	(b) (7)(F)
(b) (7)(F)	(b) (7)(F)
(b) (7)(F)	(b) (7)(F)
(b) (7)(F)	(b) (7)(F)

Personnel or agencies associated with these intakes should be notified and these areas should be given special attention during any spill.

Residential Areas

Residential areas are located southeast of the dock at Admiral's Hill in Chelsea as well as to the west of the terminal North and South Tank Farm

FIGURE 2.1
INTERNAL NOTIFICATION REFERENCES

INTERNAL NOTIFICATIONS - INCIDENT MANAGEMENT TEAM				
NAME/ POSITION/TITLE	RESPONSE TIME	OFFICE	HOME	OTHER
Jason Pociask Terminal Superintendent/ QI/ IC	1 Hour	(617) 381-2802	(b) (6)	(b) (6) CELL
Gail Prizio Field Operations Specialist/ AQI	.75 Hour	(617) 381-2840 (See Note 6)	(b) (6)	(b) (6) CELL
Jay Smith Terminal Supervisor/ AQI	0.5 Hour	(617) 381-2813	(b) (6)	(b) (6) CELL
Strike Team (Central) (See Notes 2 and 3)	<24 Hours	(815) 521-5297 (24 Hour)		
NARRT (See Note 4)	<24 Hours	(866) 285-8895 (24 Hour)		
Emergency Response Team	<6 Hours			(See Note 5) ALT
Emergency Support Group (ESG)	<6 Hours			(832) 624-7872 CELL

QUALIFIED INDIVIDUAL	
Certification:	<p>The Company grants full authority to the designated Qualified and Alternate Qualified Individuals to implement the Facility Response Plan and to:</p> <ul style="list-style-type: none">• Activate and engage in contracting with oil spill removal organizations,• Act as liaison with the pre-designated Federal On-Scene Coordinator (FOSC), and• Obligate funds required to carry out response activities.
Qualified Individual:	
Jason Pociask	52 Beacham Street (b) (6) (Home)
Terminal Superintendent/ QI/ IC	Everett, Massachusetts (b) (6) (Cellular)
Training Comments: Training is addressed in App. D.3. Training records are maintained at the site.	

Alt. Qualified Individual:	
Gail Prizio	52 Beacham Street (b) (6) (Home)
Field Operations Specialist/ AQI	Everett, Massachusetts (b) (6) (Cellular)
Training Comments: Training is addressed in App. D.3. Training records are maintained at the site.	

Alt. Qualified Individual:	
Jay Smith	52 Beacham Street (b) (6) (Home)
Terminal Supervisor/ AQI	Everett, Massachusetts (b) (6) (Cellular)
Training Comments: Training is addressed in App. D.3. Training records are maintained at the site.	

FIGURE 2.1

INTERNAL NOTIFICATION REFERENCES

INTERNAL NOTIFICATIONS - INCIDENT MANAGEMENT TEAM				
NAME/ POSITION/TITLE	RESPONSE TIME	OFFICE	HOME	OTHER
Jason Pociask Terminal Superintendent/ QI/ IC	1 Hour	(617) 381-2802	(b) (6)	(b) (6) CELL
Gail Prizio Field Operations Specialist/ AQI	.75 Hour	(617) 381-2840 (See Note 6)	(b) (6)	(b) (6) CELL
Jay Smith Terminal Supervisor/ AQI	0.5 Hour	(617) 381-2813	(b) (6)	(b) (6) CELL
Strike Team (Central) (See Notes 2 and 3)	<24 Hours	(815) 521-5297 (24 Hour)		
NARRT (See Note 4)	<24 Hours	(866) 285-8895 (24 Hour)		
Emergency Response Team	<6 Hours			
Emergency Support Group (ESG)	<6 Hours			(832) 624-7872 CELL